

ARCS PROCEDURE:	OBTAINING CEILOMETER CONFIGURATION	PRO(CEI)-010.003
Author: W. Porch		17 September 2003 Page 1 of 5

## Obtaining Ceilometer Configuration

### I. Purpose:

The purpose of this procedure is to document how RESET can obtain a configuration file for the Ceilometer.

### II. Cautions and Hazards:

None.

### III. Requirements:

- Active computer and ceilometer

### IV. Procedure:

#### A. Steps:

1. Determine the port settings.

**NOTE: You can determine the port settings by going to the Settings drop-down menu and selecting "Port settings". (Because the ceilometer is on-line, all the controls will be greyed, indicating you cannot change them, but that's okay since we only want to examine the settings.)**

2. Take the data port off-line. (Under "File", select Dataport OFF.)
3. Run a terminal program. This is usually accomplished by clicking on **Terminal** in the menu bar and selecting **Windows Terminal**. ( With luck, the TERMINAL.EXE program is properly referenced and will start right up. If not, you will need to search the hard drive for either TERMINAL.EXE or Hyperterminal (which is usually under the Accessories program group). The communications setup is 7 data bits, 1 stop bit, even parity, ignore parity, and either 2400 or 9600 baud (turn Xon/Xoff off; no flow control))
4. Once the terminal program is started, hit ENTER a few times. (If the port settings are proper, you should get the CT: prompt back from the ceilometer. If not, you will need to fix the port settings. In TERMINAL you go to "Settings:Communication". In Hyperterminal, I go to "File:Properties", then click the Configure button. Set the port settings to match the values determined earlier.)
5. Once you have the CT: prompt, log in by typing "**open** <enter>" (note: the word **open** is not echoed back so if the ceilometer is doing something you may have to repeat the "**open** <enter>" several times to get through). Eventually, you should receive the Ceilo> prompt.

<b>ARCS PROCEDURE:</b>	<b>OBTAINING CEILOMETER CONFIGURATION</b>	<b>PRO(CEI)-010.003</b>
<b>Author: W. Porch</b>		<b>17 September 2003</b> <b>Page 2 of 5</b>

6. Insert a floppy disk.
7. Activate file capture from the menu bar ("transfer" and "receive text file" for terminal; "screen capture" in hyperterminal) above the terminal window. Then, name the text file in the upper left hand box (cfg\_site\_CElyymmdd.txt). Then, select the a: drive in the lower right dialog box. Click OK and begin writing "get" requests below: (note: if this step takes more than about 2 minutes the ceilometer may time out and you will have to start over with the "open" command).
8. Type: CEILO>get algorithm.  
Sample Output:
  - NOISE SCALE: 1.7
  - MINIMUM SUM: 30
  - MINIMUM EXTCO: 6.0
9. Type: CEILO>get data\_acq.  
Sample Output:
  - AUTOADJUSTMENTS: OFF
  - DATA-ACQ. INTERVAL: 15 SEC.
  - RECEIVER
  - GAIN: H
  - BANDWIDTH: N
  - SAMPLING RATE: 10 MHz
  - TRANSMITTER
  - LENGTH OF PULSE: L
  - POWER OF PULSE: 179
  - QUANTITY OF PULSES: 64K
  - COMPENSATION
  - COARSE COMPENSATION: 13
  - FINE COMPENSATION: 125
10. Type: CEILO>get factory  
Sample Output:
  - FACTORY
  - IN POWER: 179

ARCS PROCEDURE:	OBTAINING CEILOMETER CONFIGURATION	PRO(CEI)-010.003
Author: W. Porch		17 September 2003 Page 3 of 5

- OUT POWER: 942
- COARSE COMP.: 13
- FINE COMP.: 125
- RECEIVER TEST VALUE: 430
- CLEAN WINDOW: 220mV

11. Type: CEILO>get message

Sample Output:

- MESSAGE
- ANGLE CORRECTION: ON
- HEIGHT OFFSET: 0
- NOISE H2 COMPENSATION: OFF
- PORT: DATA
- PROFILE SCALE: 100%
- TYPE: 1
- UNITS: FEET

12. Type: CEILO>get port

Sample Output:

- MAINTENANCE PORT BAWDS: 2400, E71
- DATA PORT BAWDS: 2400, E71

13. Type: CEILO>get info

Sample Output:

- CT25K 1.04 1995-05- 15
- CTLIB 1.04b 1995-05-09
- CTCLI 1.01 1995-02-28

14. Type: CEILO>get status

Sample Output:

- VOLTAGES (UNIT 0.1V)
- P12 13() M12 -122 P5G 54 M5G -55 VCA 251
- P13 129 M13 -123 P5R 50 MSR -49 BAT 138
- P18 176 PHV 2104 PFB 20 P65 781 CHA 138

RECEIVER TRANSMITTER

ARCS PROCEDURE:	OBTAINING CEILOMETER CONFIGURATION	PRO(CEI)-010.003 17 September 2003 Page 4 of 5
Author: W. Porch		

GAIN H PLEN L  
 BAND N PQTY 64K  
 SAMP 101vHz OUT 943Mv  
 SENS 100% SENS 100%  
 COMP013 125 IN 179  
 TEMPERATURES ENVIRONMENT  
 BLOWER +30C WINDOW 225mV 102%  
 CPU +35C RADIANCE 6mV  
 LASER +26C ANGLE -IDEG  
 LENS +31 C HUMIDITY NONE  
 OUTSIDE + 19C  
 INHEATER OFF OUTHEATER OFF BLOWER OFF

14. Type: CEILO>get unit\_ID  
Sample output:
  - UNIT ID: 0
15. Type: CEILO>advanced  
(This password gets you into the advanced options)
16. Type: CEILO>get value others angle  
Sample output: ANGLE: 0 DEG
17. Type: CEILO>get value others power\_of\_p
18. Type: CEILO> get value others radiance
19. Turn off file capture
20. Type "close <enter>" (you should begin to see data begin to stream in 15 seconds).
21. Close the terminal window by clicking on X in upper right corner.
22. Reconnect port by clicking on port icon in vc-view window (you should see backscattering returns being displayed in 15 seconds with a solid red line showing during the time the configuration data were being taken).
23. Send copy of the cfg\_siteCEIlyymmdd.txt file on the floppy disk to mentor and TWPPPO.

ARCS PROCEDURE:		PRO(CEI)-010.003
Author: W. Porch	OBTAINING CEILOMETER CONFIGURATION	17 September 2003 Page 5 of 5

**V. References:**

None.

**IV. Attachments:**

None.